

TABLE 1 - SUMMATION OF CFRAME(X8838) COMPUTER ANALYSIS

JOINT FIXITY INPUT		REACTIONS		MOVEMENTS	
JOINT 1	JOINT 4	JOINT 4	JOINT 4	JOINT 4	JOINT 5
X	Y	RZ	RY	X	Y
R/IN	R/IN	KIPS	KIPS	IN	IN
FIXED	FIXED	50	0	13.25	0
FIXED	FIXED	50	0	16.22	1.62
FIXED	FIXED	50	10	8.56	2.01
FIXED	FIXED	50	100	3.46	5.56
FIXED	FIXED	50	200	3.44	5.46
FIXED	FIXED	100	0	13.25	0
FIXED	FIXED	100	0	11.34	1.15
FIXED	FIXED	100	10	16.11	1.09
FIXED	FIXED	100	100	5.79	4.68
FIXED	FIXED	100	200	5.18	4.46








TABLE 1 - SUMMATION OF CFRAME(X8838) COMPUTER ANALYSIS

JOINT FIXITY INPUT		REACTIONS		MOVEMENTS	
JOINT 1	JOINT 4	JOINT 4	JOINT 4	JOINT 4	JOINT 5
X	Y	RZ	RY	X	Y
R/IN	R/IN	KIPS	KIPS	IN	IN
FIXED	FIXED	50	0	13.25	0
FIXED	FIXED	50	0	16.22	1.62
FIXED	FIXED	50	10	8.56	2.01
FIXED	FIXED	50	100	3.46	5.56
FIXED	FIXED	50	200	3.44	5.46
FIXED	FIXED	100	0	13.25	0
FIXED	FIXED	100	0	11.34	1.15
FIXED	FIXED	100	10	16.11	1.09
FIXED	FIXED	100	100	5.79	4.68
FIXED	FIXED	100	200	5.18	4.46



B

